

# iSpeed for CG0800S


## installation manual



### STEALTH INSTALL (UNDERNEATH THE CRANKSHAFT)



**WARNING: Make sure your e-bike is turned off !**

1. Place your e-bike upside down on a soft surface
2. Remove the black cable cover (2x Philips screw)
3. There are two smooth connectors, locate the one with BLACK internal color and disconnect it. (The one with RED internal is for the light)
-  **DO NOT disconnect the ribbed Torque sensor or Motor connector! (risk of damage)**
4. Place the iSpeed blackbox with the sticker facing down underneath the two cables, route the cables as shown in the picture and connect the iSpeed blackbox to the two black connectors
5. Re-install the cable cover with the 2x Philips screws and enjoy!

